


Backing For Casework Fastening

Leaking Roof Drain Replacement



Courtyard Masonry Restoration



Existing Metal Framing Replacement



Existing Masonry Cavity



Roof Masonry Restoration



New Masonry Flashing



Masonry Restoration Progress



Existing Window Condition



New Restroom Plumbing



Restroom Progress

